ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W0354	NA	Murthy and Dasappa house road
Segment No.	**Total Length (m)**	
5/S-W0354/S101820	36.25	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	36.25	77.625562	13.107040	77.625229	13.107075	W0689	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Srinivasapura Murthy and Dasappa house road in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	2500000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Improvements to Roads and Drains at Srinivasapura Murthy and Dasappa house road in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	005-17-000010
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/155/2016-17	25/11/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
20/02/2017	19/02/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		2498827.00
Phone No.	**E-Mail ID**	
9449863065		

Field Inspection Details

Number of Trees	Any Other Information	Name
6		CHANDRAPPA
Date of Inspection	**Remarks**	
04/04/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	04/04/2017	04/05/2017	COMPLETED
SE	VASU K M	04/04/2017	04/05/2017	COMPLETED
EE	MOHAN DAS HT	04/04/2017	04/05/2017	COMPLETED
AEE	SRIDHAR	04/04/2017	04/05/2017	COMPLETED
AE	CHANDRAPPA	04/04/2017	04/05/2017	COMPLETED
AE	CHANDRAPPA	04/04/2017	04/05/2017	COMPLETED

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ, ಬೆಂಗಳೂರು-24